

CONFIDENTIAL

LOCKHEED AIRCRAFT CORP.		ENGINEERING STUDY <input type="checkbox"/>		LAC -102						
		CHANGE PROPOSAL <input checked="" type="checkbox"/>								
DATE 12-19-60		AFFECTS: WSPO <input checked="" type="checkbox"/>		PROJECT <input checked="" type="checkbox"/>						
NAME OF MAJOR COMPONENT AIRPLANE		PART OR LOWEST SUBASSEMBLY 250 VA INVERTER		PART NO. & MODEL OR TYPE R1125						
TITLE OF PROPOSAL : REPLACEMENT OF R1125 INVERTER										
<p>NATURE OF PROPOSAL :</p> <ol style="list-style-type: none"> <li>1. Replace existing 250 VA Inverter (R1125 with a 500 VA Inverter (Jack &amp; Heintz F20-5). This includes removal of existing related wiring, power relay, "Keep Alive" and "Inv. Power" circuit breakers and installation of a 50 AMP circuit breaker in the CB and Fuse Panel plus wiring to the new inverter. Some re-arrangement of other equipment on the Q-bay shelf is required to provide space for the larger inverter.</li> <li>2. Prepare and issue a Service Bulletin.</li> <li>3. Fabricate appropriate Kits.</li> </ol>										
<p>REASON FOR PROPOSAL :</p> <p>To provide a larger source of 400 cycle power to satisfy existing aircraft electrical requirements and minimize premature inverter failures and consequent aborted missions. The new 500 VA Inverter will provide regulated "A" phase voltage resulting in improved performance of voltage sensitive systems which are powered by this phase.</p> <p>NOTE: This proposal is applicable to all U-2A aircraft. Inverter replacement on U-2C aircraft is included as a part of Change Proposal No. LAC-99.</p>										
ES		ESTIMATED COST AND TIME INVOLVED :								
		ADDITIONAL FUNDING REQUIRED :								
CP		<p>ESTIMATED COST FOR KITS OR PARTS : Cust #1 \$ 3,375.00 (5 Kits)</p> <p>Cust #2 \$ 20,925.00 (31 Kits)</p> <p>ADDITIONAL FUNDING REQUIRED : NONE (SP 1917) - Spares recommended on Page 2</p>								
ITEMS AFFECTED BY PROPOSAL :										
SAFETY	MISSION EFFEC- TIVENESS	PERFORM- ANCE	OPERATING PROCEDURE	INTER- CHANGE- ABILITY	WEIGHT OR WEIGHT & BALANCE	TOOLS & SUPPORT EQUIPMENT	MAINTENANCE PROCEDURE	SERVICE LIFE	FLIGHT MANUAL	MAINTENANCE MANUAL
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
EST. MAN/HRS. REQ'D. TO ACCOMPLISH CHANGE IN FIELD						16 HRS.				
SOURCE OF PARTS FOR KIT LAC						AVAILABILITY <u>12</u> WEEKS AFTER APPROVAL OR SOONER				
DISPOSITION OF SPARES AFFECTED R1125 Inverter no longer used. Leach 9022 Power Relay used in A/P circuit - All Aircraft.						25X1A				
INITIATED BY : LAC						APPROVED : WSPO				
Approved For Release 2003/01/30 : CIA-RDP81B00878R000600030071-0						2/29/60				

25X1

Approved For Release 2003/01/30 : CIA-RDP81B00878R000600030071-0

Approved For Release 2003/01/30 : CIA-RDP81B00878R000600030071-0

TO	NAME AND ADDRESS	INITIALS	DATE
1.	material	C2H	
2.	Contracts		
3.			
4.			
5.			
6.			
7.			
RETURN TO SENDER			
ACTION		CONCURRENCE	INFORMATION
COMMENT		FILE	SIGNATURE
REMARKS			
LAC-102 for approval.			
FROM			
NAME AND ADDRESS		PHONE NO.	

STATINTL

STATINTL